	ACTION	1	FOURD/FUNCTION LOCA	1 1	CDEW INDICATION	NOTES
	ACTION		EQUIP/FUNCTION LOST		CREW INDICATION	NOTES
			RPCM N1RS1 C (Type V) MDM N1 2 Srv Htr		Caution Messages:	Since the Early Comm
1	PCS Node 1: EPS: RPCM N1RS2 RPCM NIRS2 A sel RPCM Detail sel RPC [X] [X] = 10 11 cmd Open Execute	2	CBM N1 Stbd Sec 1 (Early Comm Port Ant Pwr) CBM N1 Stbd Sec 2 (Early Comm Port Ant Htr) CBM N1 Stbd Sec 3 (Early Comm Stbd Ant Pwr) CBM N1 Stbd Sec 4 Early Comm Stbd Ant Htr)		Advisory Messages: RPCM N1RS1_C Loss of Comm - NOD1 Telemetry: PCS Node 1: EPS NODE1:EPS RPCM N1RS1 C - not Active	antennas are lost, the entire Early Comm system is lost. The internal Early Comm equipment is powered off, except for the Transceiver. The Transceiver remains powered to provide survival heater power.
	Repeat				Active	These CBMs are not
	On MCC Ga	3	PMA1 Shell Htrs String A			planned to be used on 3A.
	Go to RPCM REMOVE AND REPLACE, all (SODF: OSO).					3
						String B of the Node 1 and PMA 1 Shell Heaters are nominally primary.